

FACILITY COMPLIANCE AUDIT REPORT

Division of Waste Management Solid Waste Section

UNIT TYPE:													
Lined MSWLF	LCID	YW	Transfer		Compos t		SLAS		COUNTY: Catawba				
Closed MSWLF	HHW	White goods	Incin		T&P		FIRM		PERMIT NO.: 18-12				
CDLF	Tire T&P / Collection	Tíre Monofill	Industrial Landfill	X	DEMO		SDTF		FILE TYPE: COMPLIANCE				

Date of Audit: April 29, 2010 Date of Last Audit: None

FACILITY NAME AND ADDRESS:

Duke Energy - Marshall Steam Station Industrial Landfill No. 1 8320 East NC Highway 150 Terrell, North Carolina 28682

GPS COORDINATES: N: 35.62215 W: 80.97266

FACILITY CONTACT NAME AND PHONE NUMBER:

Ed Sullivan, Corporate EHS (980) 373-3719 Duke Energy Coporation EC13K/Post Office Box 1006 Charlotte, North Carolina 28201 ed.sullivan@duke-energy.com

FACILITY CONTACT ADDRESS:

Same

AUDIT PARTICIPANTS:

Donna Burrell, Duke Power- Environmental Coordinator Ed Sulllivan, Duke Power- General Office Carlton Allred, Duke Power-Materials Coordinator Charles Gerstell, NCDENR-Solid Waste Section

STATUS OF PERMIT:

A Permit to Construct Industrial Landfill No. 1 was issued on February 25, 2010 and shall expire on February 25, 2015.

PURPOSE OF AUDIT:

Comprehensive

NOTICE OF VIOLATION(S):

None

You are hereby advised that, pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Statute or Regulations. For the violation(s) noted here, you may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

FACILITY COMPLIANCE AUDIT REPORT Division of Waste Management Solid Waste Section

Page 2 of 2

STATUS OF PAST NOTED VIOLATIONS:

N/A

AREAS OF CONCERN AND COMMENTS:

- 1. Sub-grade construction has been completed in cell #1.
- 2. Sub-grade of cell #2 was under construction at the time of inspection.
- 3. Dust was well controlled at the time of inspection.
- 4. Land clearing waste from grading activities was being burned at the time of inspection. An Open Burning Permit was obtained by Earnhardt Grading for this activity. A copy of the permit was submitted to the Solid Waste Section and received on April 12, 2010.
 - a. Smoke from the burning activity was minimal at the time of inspection.

Please contact me if you have any questions or concerns regarding this audit report.

Charles T Gerstell
Environmental Senior Specialist

Phone: (704) 235-2144.

2
Regional Representative

Delivered on <u>: 5/12/10</u> by	X	Electronic Correspondence	US Mail	Certified No. [_]

Cc: Mark Poindexter, Field Operations Branch Supervisor

Deborah Aja, Western District Supervisor

Donna Burrell (donna.burrell@duke-energy.com)
Carlton Allred (jcallred@duke-energy.com)